





PSF 200 Tool Box Power Steering Fluid Exchanger





PSF 200 Troubleshooting

No Power

- Check battery connectors, power cord and switches.

No Suction

- Clean or replace pump head

Pump runs but no fluid

- Check for obstruction in the tank or inlet hose at the pump.

PSF 200 Power Steering Flush Toolbox

7.1

Fasteners

1030	Machine Screw and nuts for fastening PSF 200 pumps
1031	Plastic Black Hose Clip

Hardware

2008	Power Cord Strain Relief
2011	Strain Relief for PSF Remote Box
2070	Plastic Tool Box

Metal Body Parts

3051	Metal Cover Plate for Remote box
3080	Metal Bracket for Pump

Plumbing

4010	3/8" id kuri tech polyurethane tubing
4035	1/4" Inline Filter
4070	3/8" Black stiff hose

Electrical

5006	Battery Clamps
5007	Power Cord
5018/19	Marrets
5026	Blue Spade Connector
5050	Plastic Power Receptacle for Remote Box
5051	Electrical Wire for Remote Box
5052	Plastic 3/4" x 1/2" Bushing
5055	Square Plastic Switch
5057	PSF Remote Box Assembly
5070	Pump for PSF 200

Fittings

6001	3/8" Hose Barb 1/4" Female Thread
6040	Nylon 3/8" x 3/8" 90° hose mender